

Qty:

1 Um:

Each

: SUPPORT BRACKET

: D23623

: N/A

D2362 REV E1

: 11/14/2006



Date:

Monday, 11/13/2006 12:38:19 PM

User:

Chantal Lavoie

Process Sheet

Drawing Name

Part Number

Material

Due Date

Drawing Number

Project Number

Drawing Revision

Customer

Job Number

: CU-DAR001 Dart Helicopters Services : 29435

Estimate Number

: 10260

P.O. Number This Issue

: NIA

: 11/13/2006

S.O. No. : NIA

: NC

Prsht Rev. :-N/A First Issue

Previous Run Written By

Checked & Approved By

Comment

Type

'MACHINED PARTS

: 28550

Added inspection level 8

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description: Step Support Casting

1.0 D2265

Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

> Step Support Pick:

Qty Part Number

Description 1 D2265

Step Support

Batch

2.0 HAAS1 HAAS CNC VERTICAL MACHINING #1

Comment: Machine per folio D2362-3

3.0 QC2 INSPECT PARTS AS THEY COME OFF MACHINE



Comment: Inspect Level 2

4.0 QC8 SECOND CHECK



Comment: SECOND CHECK

SMALL FAB 1 5.0

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Deburr

Er 06/11/13 x

Dart Ae	rospace L	.td							
W/O:			WC	RK ORDER CHANGES	3				
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		,							
		:							
Part No	-	PAR #:	Fault Categ	jory:				*	
							d:	_ Date: _	
NCR:		1 1 2	WORK ORDE	R NON-CONFORMAN	CE (NCR	(1)			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	Sign & Date	Verific Secti		Approval Chief Eng	Approval QC Inspector
				,					

NOTE: Date & initial all entries

Monday, 11/13/2006 12:38:19 PM Date: User: Chantal Lavoie **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services **Drawing Name: SUPPORT BRACKET** Job Number: 29435 Part Number: D23623 Job Number: Seq. #: **Machine Or Operation: Description:** POWDER COATING POWDER COATING 6.0 M101575 **Comment: POWDER COATING** 06/11/13 Powder Coat Gloss White (Ref 4.3.5.1)as per Dart QSI 005 4.3 INSPECT POWDER COATINHEMICAL CONVERSION 7.0 QC3 Comment: INSPECT POWDER COAT D23971 8.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) **Rubber Cushion** Pick: **Qty Part number** Description D2397-1 Rubber Ba 1768 9.0 D23973 Rubber Cushion Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) **Rubber Cushion** Pick: **Qty Part number** Description Batch D2397-3 Rubber B27/69 06-11-14 SMALL FAB 1 SMALL & MEDIUM FAB RESOURCE 1 10.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 Bond rubber D2397-1 followed by D2397-3 using contact cement Batch M 100374. as per Dwg D2362 INSPECT WORK TO CURRENT STEP 11.0 QC5 Comment: INSPECT WORK TO CURRENT STEP PACKAGING RESOURCE #1 12.0 **PACKAGING 1 Comment: PACKAGING RESOURCE #1** Identify and Stock Location:

Dart Aerospace Ltd

W/O:		WORK ORDER CH	HANGES	, , , , , , , , , , , , , , , , , , , 			
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #: Fault Category:	NCR: Yes	No DQ	A: D	_ Date: ₫	-11115

QA: N/C Closed: ____ Date: ____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B		Verification	Annaval	Annessal		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector		
	*			-						
					2					
		e _v :						1		
					- 1		-			

NOTE: Date & initial all entries

Date:

Monday, 11/13/2006 12:38:19 PM

User:

Chantal Lavoie

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: SUPPORT BRACKET

Job Number: 29435

Part Number: D23623

Job Number:



Seq. #:

Machine Or Operation:

Description:

13.0

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE



Job Completion




C.L00/11/14

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	P	ROCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
				1-3-1						
		-								
Part No		PAR #:	Fault Category:	NC	R: Yes	No DQ	A:	_ Date: _		
					QA: I	N/C Close	d:	_ Date: _		

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B		Verification	A	A			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approvat QC Inspecto			
					2,						
12 0											
A .		.									
						,	:				

NOTE: Date & initial all entries



DART AEROSPACE LTD	Work Order: 29436
Description: Step Support Bracket	Part Number: D2362-3
Inspection Dwg: 02362 , Rev:	Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Re est	Method of Inspection	Comments
1,28	20.03	1278				
1200	+ 8010	1.210				
1, 000	+ 0.010	10800				
0.80	20030	0.770			*.5	,
0.77	*to:030	6.80				• •
3.074	20010	3068		<u>,</u>		
6.74	D0030	0.332				
1,500 :	\$8.010	1.499				
\$ 0257	to.001.	6:258				
1.88	±0-030	1.870				
100	\$2030	0.988				
0-257	100/o	0:059				7
0.075	±0030	0.761	/	•		
	•			*****		·
						: :
1	3.		-			2
		· j				`
						

Measured by:	ch.	Audited by:	J.L.	Prototype Approval:	ALL
Date:	06/u/13	Date:	06/11/13	, Date:	- W (1)

Rev	Date	Change	Revised by	Approved
Α		New Issue	KJ/JLM	

